

2063

**B. E. (Mechanical Engineering)**  
**Fifth Semester**

**MEC-502: Computer Aided Design and Manufacturing (CAD/CAM)**

**Time allowed: 3 Hours**

**Max. Marks: 50**

**NOTE: Attempt five questions in all, including Question No. 1 (Section-I) which is compulsory and selecting two questions each from Section B- C.**

x-x-x

Section-A

1.

- a) A 2 degree B-spline curve has 6 control points. Find the continuity and no. of segments of the curve. 5x2  
=10
- b) How tool can be changed in part program.
- c) Write Hermite Matrix ( $M_H$ ) for Hermite cubic splines.
- d) Describe axis nomenclature for CNC lathe and milling machines.
- e) Find the transformed coordinates when a line [(3, 4), (4, 2),] is rotated about z- axis by an angle of  $90^\circ$  in anticlockwise direction?

Section-B

2.

- a) A Cubic Bezier curve is defined by control points (20, 20), (60, 80), (120, 100) and (150, 30). Find the equation of the curve and its midpoint coordinates. 7
- b) Describe the advantage and disadvantages of soft automation? 3

3.

- a) Find the new position of the pentagon [A(3, 2), B(5, 2), C(5, 3), D(4, 4), E(3, 5)] after its rotation by  $90^\circ$  anti-clockwise about A point and then reflection about a line passing through (5, 2) and parallel to y-axis? 7
- b) Write parametric and nonparametric equations of line and circle with example. 3

4.

- a) Explain how the product cycle is revised with introduction of CAD/CAM. 4
- b) What is Geometric Modeling. Discuss the need of Geometric modeling 3
- c) Discuss the applications of CAD/CAM in automobile industry. 3

Section-C


5.

- a) Describe the basic elements of constructive solid geometry model. Discuss the CSG tree and data tables with examples. 7
- b) Mention the need for surface modeling. Write the parametric equation of plane surface defined by points A, B and C. 3

P.T.O.

(2)

6. Write a complete part program to machine the outline of the geometry as shown in the diagram. The component is 4 mm thick. The milling tool used is 4 mm in diameter. Consider spindle speed as 850 rpm and feed as 130 mm/min. Assume suitable data if necessary.



10

7. a) Briefly explain the drilling canned cycle in manual part programming with suitable example. 4  
 b) What are the various ways to specify a circle in APT. Explain with examples? 3  
 c) What is the need of Euler's Formula in b-rep? Discuss Euler's Formula by taking suitable example. 3

x-x-x