Exam.Code:0936 Sub. Code: 33768

(6)

B.E. (Electrical and Electronics Engineering)

	Sixth Semester PC-EE-602: Power Electronics	
Time		Marks: 50
NOT	E: Attempt <u>five</u> questions in all, including Question No. I which is and selecting two questions from each Part.	
	<i>x-x-x</i>	
1.	(i) Explain firing angle and conduction angle as associated with an SCR.	(2)
	(ii) Draw a circuit of an UJT working as relaxation oscillator for an SCR. Draw the	waveform
	of output voltage obtained.	(2)
	(iii) Discuss the process of Load Commutation for an SCR.	(2)
	(iv) Draw the circuits of Resistive firing circuit and full wave RC firing circuit.	(2)
	(v) What is meant by 'Line Commutated Inverter'.	(2)
	PART-A	
2.	(i) Draw and explain turn-on characteristics of a thyristor.	(5)
	(ii) Draw and derive the expression for Static Equalising Circuit for an SCR.	(5)
3.	(i) For a single-phase full converter with source inductance Ls, explain its working angle μ and firing angle α =0 degrees. Draw the waveforms for current and voltag (ii) Explain the working of single phase full- wave mid-point converter with RL loa waveform for input and output voltage. Sketch the waveforms for output current discontinuous current mode(β < π + α).	ges. (5) ad. Draw the
4.	(i) For a Buck-Boost DC regulator, explain its working and derive the expression for	or output
	voltage.	(5)
	(ii) For type-A chopper, dc source voltage 230 V , load resistance =10 ohms. Take	
	drop of 2 V across chopper when it is on. For a duty cycle of 0.4, calculate averag values of output voltage.	
	PART-B	
5.	(i) Draw the circuit of four quadrant chopper and explain its working in second qu	
	(ii) Explain the working of voltage commutated chopper and draw the waveform	for output
	Vc, Ic and Vo.	? (6)
6.	(i) A three-phase full converter, fed from 3-phase, 400 V, 50 hz source is connected R=10 ohms, E= 350 V and large inductance so that output current is ripple free. Opower delivered to load and input pf for firing angle of 30 degrees. (ii) For a single phase 2-pulse full wave thyristor converter, draw its circuit, the input waveform, show the table of conduction of thyristors for firing angle=1 sketch the output voltage and derive its expression.	Calculate the (5) three-phase
	(i) A single phase full converter feeds power to RLE load with R=6 ohms, L=6mH a V.The ac source voltage is 230V,50 hz.For continuous conduction ,find the averag load current for a firing angle delay of 50 degrees. In case one of the four SCRs get	e value of

circulating current mode. Also derive the condition for firing angles for its operation .

(ii) Draw a three-phase dual converter, its equivalent circuit and explain its operation in

circuited due to a fault, find the new value of average load current.